

SIMtrace - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
1424	Bug	Closed	High	simtrace pinout of tps73633 is wrong	tsaitgaist	02/20/2016 06:45 PM	
1425	Bug	Closed	High	simtrace pinout of bootloader / reset switch is wrong	tsaitgaist	02/20/2016 06:44 PM	
1426	Bug	Closed	Normal	simtrace component names on silk screen unreadable	tsaitgaist	02/20/2016 06:44 PM	
1427	Bug	Closed	High	simtrace BC847 footprint has B / E switched	tsaitgaist	02/20/2016 06:44 PM	
1431	Bug	Closed	High	use PA16 for UDP_PUP as required by SAM-BA	tsaitgaist	02/20/2016 06:44 PM	
1432	Bug	Closed	Normal	simtrace: bootloader switch without function	tsaitgaist	02/20/2016 06:44 PM	
1434	Bug	Closed	High	socket for FPC SIM adapter is mechanically incompatible with rebelsim fpc	tsaitgaist	02/20/2016 06:43 PM	
1435	Bug	Closed	Normal	sim card detect does not work (SW_SIM)	tsaitgaist	02/20/2016 06:43 PM	
1437	Bug	Closed	Immediate	on resistance of bus switch not acceptable, at least not for Vcc	tsaitgaist	02/20/2016 06:42 PM	
1446	Bug	Closed	High	test ticket to check notification	tsaitgaist	02/20/2016 06:41 PM	
1447	Bug	Closed	High	C14 is too far from LDO, causes oscillation	tsaitgaist	02/20/2016 06:41 PM	
1448	Bug	Closed	High	silk screen print on top of soldering pads	tsaitgaist	02/20/2016 06:41 PM	
1449	Bug	Closed	High	no solder mask between the pads of the AT91SAM7	tsaitgaist	02/20/2016 06:41 PM	
1450	Bug	Closed	Urgent	FTDI serial connector power supply	tsaitgaist	02/20/2016 06:40 PM	
1452	Bug	Closed	High	move C14 directly to pad 4 of IC2	tsaitgaist	02/20/2016 06:40 PM	
1456	Bug	Closed	Normal	make sure there is solder mask between pads of SAM7	tsaitgaist	02/20/2016 06:39 PM	
1459	Bug	Resolved	Low	send a flag tagging the ATR from the card	laforge	02/06/2021 01:32 PM	
1840	Bug	Closed	Normal	SIMtrace Firmware	laforge	11/22/2016 05:56 PM	
2614	Bug	Rejected	Normal	simtrace_hdr randomly appears in APDU payload	lukash	09/28/2022 08:06 AM	