

SIMtrace - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Related issues |
|------|---------|----------|----------|---|------------|---------------------|----------------|
| 1724 | Feature | Rejected | Low | extend wireshark dissector for SIM/USIM traces | | 09/28/2022 08:07 AM | |
| 1455 | Feature | Closed | High | try to improve trace width / blocking caps | tsaitgaist | 02/20/2016 06:39 PM | |
| 1454 | Feature | Closed | High | add "sysmocom" text into the copper layer | tsaitgaist | 02/20/2016 06:39 PM | |
| 1453 | Feature | Closed | High | Move C21 closer to VCC_SIM pad | tsaitgaist | 02/20/2016 06:39 PM | |
| 1451 | Feature | Closed | Normal | Atmel SAM3S to replace SAM7S | tsaitgaist | 02/20/2016 06:40 PM | |
| 1445 | Feature | Closed | Low | Some component labels (resistors/capacitors) are not readable | tsaitgaist | 02/20/2016 06:41 PM | |
| 1444 | Feature | Closed | High | Adapt to different shottky diode footprint | tsaitgaist | 02/20/2016 06:41 PM | |
| 1443 | Feature | Closed | High | Adapt to different SPI flash (foot print) | tsaitgaist | 02/20/2016 06:42 PM | |
| 1442 | Feature | Closed | High | Make LED footprints 0805 instead of 0603 | tsaitgaist | 02/20/2016 06:42 PM | |
| 1441 | Feature | Closed | High | Use through-hole 2.5mm jack | tsaitgaist | 02/20/2016 06:42 PM | |
| 1440 | Feature | Closed | High | Use through-hole mini-USB-B socket | tsaitgaist | 02/20/2016 06:42 PM | |
| 1439 | Feature | Closed | Low | move ERASE and TEST jumper a tint bit, so a 1x4pin header works | tsaitgaist | 02/20/2016 06:42 PM | |
| 1438 | Feature | Closed | Normal | add ID-1 slot to SIMtrace | tsaitgaist | 02/20/2016 06:42 PM | |
| 1436 | Feature | Closed | Normal | add VCC_PHONE to an unused GPIO | tsaitgaist | 02/20/2016 06:42 PM | |
| 1433 | Feature | Closed | Normal | use 90 degree angled jumpers for ERASE and TEST | tsaitgaist | 02/20/2016 06:44 PM | |
| 1430 | Feature | Closed | Normal | clearly indicate location of 'pin 1' of components and connectors | tsaitgaist | 02/20/2016 06:44 PM | |
| 1429 | Feature | Closed | Normal | usb jack type is really hard to manually solder | tsaitgaist | 02/20/2016 06:44 PM | |
| 1428 | Feature | Closed | Normal | increase default trace width in simtrace pcb | tsaitgaist | 02/20/2016 06:44 PM | |