

SIMtrace - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated | Related issues |
|------|---------|--------|-----------|---|------------|---------------------|----------------|
| 1840 | Bug | Closed | Normal | SIMtrace Firmware | laforge | 11/22/2016 05:56 PM | |
| 1456 | Bug | Closed | Normal | make sure there is solder mask between pads of SAM7 | tsaitgaist | 02/20/2016 06:39 PM | |
| 1452 | Bug | Closed | High | move C14 directly to pad 4 of IC2 | tsaitgaist | 02/20/2016 06:40 PM | |
| 1450 | Bug | Closed | Urgent | FTDI serial connector power supply | tsaitgaist | 02/20/2016 06:40 PM | |
| 1449 | Bug | Closed | High | no solder mask between the pads of the AT91SAM7 | tsaitgaist | 02/20/2016 06:41 PM | |
| 1448 | Bug | Closed | High | silk screen print on top of soldering pads | tsaitgaist | 02/20/2016 06:41 PM | |
| 1447 | Bug | Closed | High | C14 is too far from LDO, causes oscillation | tsaitgaist | 02/20/2016 06:41 PM | |
| 1446 | Bug | Closed | High | test ticket to check notification | tsaitgaist | 02/20/2016 06:41 PM | |
| 1437 | Bug | Closed | Immediate | on resistance of bus switch not acceptable, at least not for Vcc | tsaitgaist | 02/20/2016 06:42 PM | |
| 1435 | Bug | Closed | Normal | sim card detect does not work (SW_SIM) | tsaitgaist | 02/20/2016 06:43 PM | |
| 1434 | Bug | Closed | High | socket for FPC SIM adapter is mechanically incompatible with rebelsim fpc | tsaitgaist | 02/20/2016 06:43 PM | |
| 1432 | Bug | Closed | Normal | simtrace: bootloader switch without function | tsaitgaist | 02/20/2016 06:44 PM | |
| 1431 | Bug | Closed | High | use PA16 for UDP_PUP as required by SAM-BA | tsaitgaist | 02/20/2016 06:44 PM | |
| 1427 | Bug | Closed | High | simtrace BC847 footprint has B / E switched | tsaitgaist | 02/20/2016 06:44 PM | |
| 1426 | Bug | Closed | Normal | simtrace component names on silk screen unreadable | tsaitgaist | 02/20/2016 06:44 PM | |
| 1425 | Bug | Closed | High | simtrace pinout of bootloader / reset switch is wrong | tsaitgaist | 02/20/2016 06:44 PM | |
| 1424 | Bug | Closed | High | simtrace pinout of tps73633 is wrong | tsaitgaist | 02/20/2016 06:45 PM | |