Issues

#	Project	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
3711	SIMtrace 2	Feature	New	Normal	Add screw holes for permanent installations	mschramm	11/01/2023 08:28 PM	
3038	multi-voltage USB UART	Feature	New	Normal	Add mounting holes?		03/07/2018 02:12 AM	
3037	multi-voltage USB UART	Feature	Resolved	Low	Align the space between JP2 and JP3 to 2.54mm	mschramm	08/23/2018 06:44 PM	