

SIMtrace - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
2614	Bug	Rejected	Normal	simtrace_hdr randomly appears in APDU payload	lukash	09/28/2022 08:06 AM	
1864	Support	Closed	Normal	Windows drivers		12/07/2016 10:06 AM	
1840	Bug	Closed	Normal	SIMtrace Firmware	laforge	11/22/2016 05:56 PM	
1456	Bug	Closed	Normal	make sure there is solder mask between pads of SAM7	tsaitgaist	02/20/2016 06:39 PM	
1451	Feature	Closed	Normal	Atmel SAM3S to replace SAM7S	tsaitgaist	02/20/2016 06:40 PM	
1438	Feature	Closed	Normal	add ID-1 slot to SIMtrace	tsaitgaist	02/20/2016 06:42 PM	
1436	Feature	Closed	Normal	add VCC_PHONE to an unused GPIO	tsaitgaist	02/20/2016 06:42 PM	
1435	Bug	Closed	Normal	sim card detect does not work (SW_SIM)	tsaitgaist	02/20/2016 06:43 PM	
1433	Feature	Closed	Normal	use 90 degree angled jumpers for ERASE and TEST	tsaitgaist	02/20/2016 06:44 PM	
1432	Bug	Closed	Normal	simtrace: bootloader switch without function	tsaitgaist	02/20/2016 06:44 PM	
1430	Feature	Closed	Normal	clearly indicate location of 'pin 1' of components and connectors	tsaitgaist	02/20/2016 06:44 PM	
1429	Feature	Closed	Normal	usb jack type is really hard to manually solder	tsaitgaist	02/20/2016 06:44 PM	
1428	Feature	Closed	Normal	increase default trace width in simtrace pcb	tsaitgaist	02/20/2016 06:44 PM	
1426	Bug	Closed	Normal	simtrace component names on silk screen unreadable	tsaitgaist	02/20/2016 06:44 PM	