

## SIMtrace - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
1437	Bug	Closed	Immediate	on resistance of bus switch not acceptable, at least not for Vcc	tsaitgaist	02/20/2016 06:42 PM	