

## UmTRX - Feature #1515

### Heat dissipation and mounting issue

02/19/2016 10:52 PM - 9600

<b>Status:</b> New	<b>Start date:</b>
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b> Andrey	<b>% Done:</b> 0%
<b>Category:</b> Hardware	<b>Spec Reference:</b>
<b>Target version:</b> UmTRXv2.2	
<b>Resolution:</b>	
<b>Description</b>	
Heat dissipation and mounting issue.	
[Migrated from old Google Code tracker]	