

## OsmoBSC - Bug #2382

### T3105 not consistently communicated to all BTS models

07/20/2017 08:49 AM - laforge

<b>Status:</b> New	<b>Start date:</b> 07/20/2017
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b>	
<b>Target version:</b>	
<b>Spec Reference:</b>	
<b>Description</b>	
T3105 is specified via the VTY in units of milli-seconds	
git grep -i t3105 shows that	
<ul style="list-style-type: none"><li>• OM2000 + BS-11 is using the value from the VTY</li><li>• bts_nokia_site has a related FIXME</li><li>• ipa/osmo doesn't seem to use the VTY value at all</li></ul>	

#### History

#1 - 03/05/2018 07:02 PM - laforge

- Project changed from OpenBSC to OsmoBSC

- Category deleted (libbsc)