

OsmoSDR - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
1468	Feature	Rejected	Normal	try to fit 2.5mm audio jack footprint (UART) on back side	laforge	02/20/2016 08:23 PM	
1469	Feature	Rejected	Normal	make sure sam3u chip id is present in Usb Serial Number	laforge	02/20/2016 08:23 PM	
1472	Feature	Rejected	Normal	connect ADSCK to a DQS capable FPGA pin	laforge	02/20/2016 08:23 PM	
4937	Feature	Rejected	Normal	Beginner		01/08/2021 03:56 PM	
4938	Feature	Rejected	Normal	Telephone design	efistokl	01/08/2021 03:56 PM	