

OsmoSDR - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated	Related issues
1466	Feature	Rejected	High	add footprint of 2x5pin 1.27mm pitch SWD connector	laforge	02/20/2016 08:23 PM	
1470	Feature	Rejected	High	implement DFU bootloader in first 16k of flash	laforge	02/20/2016 08:23 PM	
1471	Feature	Rejected	High	implement and test FPGA flashing via sam3u	laforge	02/20/2016 08:23 PM	
1473	Feature	Rejected	High	verify if 80Mhz rate between ADC and FPGA works	laforge	02/20/2016 08:23 PM	